

Saab-MFI 15-200/Saab-MFI 15-200 A Modification Bulletins issued to date

Number	Title	Date
MB.15.001	Incorporation of check-valve in the fuel system	1973-09-14
MB.15.002	Installation av fällningsanordning, väljarpanel samt lastbalkar för transport av förnödenheter (In Swedish)	1974-02-18
MB.15.003	Konvertering till sporrställsversion samt installation av skidor (In Swedish)	1974-02-25
MB.15.004	Radiokylning (In Swedish)	1974-03-05
MB.15.005	Förskjutning av landställsben i ok (In Swedish)	1974-03-06
MB.15.006	Solskydd i huv (In Swedish)	1974-03-06
MB.15.007	Installation av taxiljus (In Swedish)	1974-03-06
MB.15.008	Installation av förtöjningsring i vingstötta (In Swedish)	1974-03-06
MB.15.009	Införande av 3:e stol (In Swedish)	1974-03-07
MB.15.010	Ventilation huv (In Swedish)	1974-03-12
MB.15.011	Införande av temperaturövervakning NiCa batteri (In Swedish)	1974-03-12
MB.15.012	Monering av extratank (In Swedish)	1974-09-03
MB.15.013	Montering av luftskopan i huv (In Swedish)	1974-10-25
MB.15.014	Tryckbrickor landställsinfästning (In Swedish)	1974-10-24
MB.15.015	Installation nödsändare (In Swedish)	1974-11-07
MB.15.016	Luftskopa kropp (In Swedish)	1974-11-07
MB.15.017	Installation Oil separator	1975-02-17
MB.15.018	Replacement of gasket in Bendix fuel flow divider	1975-02-17
MB.15.019	Modifiering av HF-receiver	1975-05-23
MB.15.020	Ventilation canopy MFI 15	1975-12-08
MB.15.021	Radio cooling MFI 15	1975-12-08
MB.15.022	Securing of bolts for elevator attaching to fin	1975-12-08
MB.15.023	Clearance between skin of fin trailing edge and skin of rudder leading edge	1976-03-09
MB.15.024	Re-numbering of fixture for elevator rear bellcrank	1976-03-19
MB.15.025A	Replacement of faulty engine mounts	1976-04-08
MB.15.026	Improvement of sealing between fuel tank access cover and frame on wing tanks	1976-04-08
MB.15.027	Installation ELT and Homer	1976-06-16
MB.15.028	Pressure plates, main gear installation	1976-06-24
MB.15.029	Bolts in brackets between fin and fuselage	1976-07-01
MB.15.030	Replacement of engine instrument and fuel gauge	1976-07-30
MB.15.031	Kit for replacement of fuel pump 6127120-045	1976-08-19
MB.15.032	Re-location of flap follow-up cable	1976-09-21
MB.15.033	Hooking up of EGT light to the lighting rheostat	1977-01-14
MB.15.034	Elevator connection to torque tube	1977-02-14
MB.15.035	Drainage of fuel filter	1977-03-30
MB.15.036	Connecting of light for EGT-indicator L3-8	1977-05-16
MB.15.037	Reinforcement of bulkhead, wing strut fitting - main gear cradle	1977-06-07
MB.15.038	Replacement of flasher for anti-collision light	1977-06-27
MB.15.039	Installation of preamplifier for UHF	1977-10-11
MB.15.040	Installation of VHF COM antenna CCC VFS-10-90	1977-10-25
MB.15.041	Installation of choke in audio amplifier 1650051-10-1	1977-12-09
MB.15.042	Replacement of suction indicator	1978-02-22
MB.15.043	Induction air filter installation	1978-10-30

Saab-MFI 15-200/Saab-MFI 15-200 A Modification Bulletins issued to date

Cont.

Number	Title	Date
MB.15.044	Pressure plate, main gear installation	1978-10-30
MB.15.045	Spring in alternate air chamber	1978-11-30
MB.15.046	Torque tubes 5803001-10-1 pedal assy	1979-01-16
MB.15.047	Sealing of fuel tank access cover	1979-04-24
MB.15.048	Replacement of original aileron	1979-09-26
MB.15.049	Replacement of waring panel	1979-10-16
MB.15.050	Replacement of starter switch	1980-10-28
MB.15.051	Replacement of vibration insulataor	1982-01-29
MB.15.052	Replacement of brake arm rudder control assy	1982-03-23
MB.15.053	Filter air intake	1985-11-12
MB.15.054A	Starter reley	1985-11-08
MB.15.055	Removal of alternate air duct and alternate air control	1985-11-12
MB.15.056	Dome light	1987-01-08
MB.15.057	Installation bolts, Main landing gear	1990-06-26