

## Saab-MFI 15-200/Saab-MFI 15-200 A

### MFI-15 Service Bulletins issued to date

---

Number	Title	Date
SB.15.001	Förskjutning av landställsben i ok (In Swedish)	1973-08-30
SB.15.002	Spel mellan motorfundament och motor (In Swedish)	1973-08-30
SB.15.003	Inspektion av alternativluftboxens spjällaxel (In Swedish)	1974-04-16
SB.15.004	Canopy-mounted side airscoops	1975-04-03
SB.15.005	Replacement of instrument module 6127116-001	1976-09-15
SB.15.006	Replacement of electric fuel pump 6127120-045	1976-09-15
SB.15.007	Throttle and mixture controls	1976-12-02
SB.15.008	Insp of sheard rivets and cracks 003-014	1976-12-15
SB.15.009	Replacement of air spring cylinder 6127139-011 (5801537-001)	1977-08-12
SB.15.010	Replacement of flashers for anticollision light as spare parts	1977-08-26
SB.15.011	Check of play between pedals and brake master cylinders	1977-09-19
SB.15.012	Engine baffle plate, LH forward 5804102-10-1	1978-01-27
SB.15.013	Flexible control, alternate air	1978-03-09
SB.15.014	Replacement of fuel quantity transmitter 9301804-10-1	1978-11-30
SB.15.015A	Alternate fuel filter	1979-03-01
SB.15.016	Nose gear lower fitting	1979-03-22
SB.15.017	Upper attaching cone, nose gear installation	1979-04-24
SB.15.018	Replacement of warning panel	1979-10-23
SB.15.019A	Alternate air chamber assy	1979-12-03
SB.15.020	Rudder trim tab	1979-12-04
SB.15.021	Fuel quantity indicator	1979-12-11
SB.15.022	Arms 5803002-10-1 and 10-2 in the rudder pedal assy	1980-03-04
SB.15.023	Nose wheel tyre and tube	1980-04-03
SB.15.024	Cracks in sheet metal parts wing carry through	1982-02-15
SB.15.025A	Aileron attachment bolts	1984-02-28
SB.15.026	Radio Noise Filter	2000-12-05
SB.15.027	Inspection of fuselage skin panel and doublers at cut-out for MLG legs	2006-10-16